


Heat shield inside



measured the thickness of the drag plate.... varies between 1.41mm and 1.82mm  
Have to talk to a mechanic if he can grind the plate flat.



Heat shield outside

the shield touches the gear screw #23A  
filed the screw head flatter and one problem was solved